


REPAIR KIT FOR ELONGATED HOLE
IN CARBURETOR HEAT AIR BOX
CONTROL ARM. P/N FAP-03



-
- CONTROL WIRE HOLE
 - AIR BOX CONTROL ARM.
 - NEW STAINLESS PLATE.
 - MOUNTING SCREWS.
 - DRILLED BOLT .187 DIA
 - WASHERS
 - NUT

***** SIMPLE REPAIR *****
PLACE NEW STAINLESS PLATE OVER
OLD ELONGATED HOLE. DRILL (2)
HOLES THRU AIR BOX ARM. ATTACH
PLATE. CHECK FOR PROPER OPERATION.